




Baxter Creek



* denotes the sample had < 500 specimens, which may result in an incorrect IBI score

Baxter Creek Watershed



Watershed Monitoring

- Surface Water
- Underground
- Bioassessment Site

Roads

- Freeway
- Major Street
- Minor Street



A	BAX030	Baxter Creek	Booker T. Anderson Park
B	BAX045	Baxter Creek	At Gateway restoration Site

